



FBSH-2228 Assembly Instructions, page 1 of 2

STEP 1



TOOLS INCLUDED



NOTE:

Use care when
inserting spacer, so
not to lose the spacer
inside the base.

3/8\"-16 x 2\" LONG
SOCKET HEAD
SCREW



FBSH-2228 Assembly Instructions, page 2 of 2

STEP 2

